From: Wallingford, Jonni B.

To: <u>Sheldrake, Sean; Zhen, Davis</u>

Cc: Scott Coffey; younghs@cdmsmith.com

**Subject:** Fish Acoustics Oversight

**Date:** Monday, October 1, 2018 8:56:15 AM **Attachments:** IMG 20181001 075419813 HDR.jpq

IMG 20181001 075354806.jpg IMG 20181001 081100291 HDR.jpg IMG 20181001 083516686 HDR.jpg IMG 20181001 083902266 HDR.jpg

## Good morning,

The Pre-RD group is currently stationed at target location PDI-AR-A24 (SIL array) and has retreived the acoustic release. Benchmark GPS coordinates were taken at PH-1 prior to departing SIL using a Trimble GPS unit. An AED, first aid kit, spill kit, floatation device, radio, and sediment decontamination equipment are aboard the NRC vessel.

The Pre-RD group is recording serial numbers, tilt degrees, memory and battery status for the receivers and the acoustics prior to retrieval. A recovery GPS point was collected as the acoustic release was pinged and another point will be collected during deployment. Included are photos of the vessel equipment and acoustic retrieval (AR-A24).

Jonni (b) (6)

Photo 1: spill kit below vessel

?

Photo 2: AED and first aid kit

?

Photo 3: preparing to launch from SIL

?

Photo 4: acoustic release is pinged

?

Photo 5: retrieval of mooring, hosing down sediment

?